

Diebold Vault Door: 3 of 4**Kolekcja:** American 19th-20th Century Safes**Muzeum:** Historic Padlocks and Safes**Właściciel:** oshkoshlock**Stan eksponatu:** Nie określono

Opis: Diebold Safe & Lock Company (Canton, Ohio-USA) - Circa 1920. This is all the workings from a vault door - removed from the 3" thick steel slab. It has been re-mounted on heavy boards in the precise original configuration.

There are 32 pictures total, This set shows:

"a."----- The three movement timelock. Notice the rectangular slot on the lower right hand side. This slot accepts the bar -- allowing the bolts to be retracted - and the door to open.

"b." ---- Picture "7" shows the point at which the alarm wire - which surrounds the door -- makes connection with a similar contact on the door frame.